



# ARCTIC CAT<sup>®</sup>

## SERVICE BULLETIN

**Date:** November 16, 2018

**Product Line:** Snowmobile

**Bulletin No:** BS201810

**Subject:** ECM Reprogramming

**Affected Models:** All 2014-2018 7000 models

■ **NOTE:** Refer to **Cat Tracker Online** to obtain the list of affected VIN's from your inventory by selecting the "Service" tab, then the "Bulletin Display" tab. Specific criteria is required to be selected. Example: Bulletin Type-All, Product Type-SNOW, Bulletin Number BS201810 and Bulletin Year 2018.

---

**Condition:** There have been improvements to the final version of the ECM mapping and should be applied to the affected models.

**Solution:** Reprogram the ECM according to the instructions included with the CATT II Tool. Once the ECM has been reprogrammed, log onto Cat Tracker Online, select the bulletin BS201810, and file the warranty claim.

**Warranty:** A labor allowance of 0.2 hr will be paid per affected snowmobile.

■ **NOTE:** It is required to enter the current mileage of each affected model.

|  |
|--|
|  <b>ATTENTION</b> |
|--|

|  |
|--|
| To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to November 16, 2019. All warranty claims directly related to this issue will not be honored after November 16, 2019, without prior approval. |
|--|